









 Model OPTIMA 8360
PerkinElmer Serial No. 07851504205
Preventive Maintenance
C.S.E. Signature I. RAYTER MR
Customer Signature _____
Date 8.10.2024
Next Preventive Maintenance Due Date 10.2025










 Hewlett-Packard
 11311 Chinden Blvd.
 Boise, ID 83714 U.S.A.

Serial No. CNFF923346
 Número de Serie
 제품 번호
 Número de Producto
 Product No. CE956A

220 - 240V ~ AC
 50/60Hz, 3.0A
 Manufactured: 제조
 Manufactured: January, 2015
 A/S 전화: (02) 1588-3003
 제조자 캐논 중산 상사

25503/SDPPI/2012
 2141

KCC - CMM - HPQ - BOISB - 1002 - 01
 KETI XU100058 - 11002 RU6-8184
 > PET < SITE:ZS2 JH JS-1PT

Número de Modelo para Regulaciones:
 RMN: 관리 모델 번호
 BOISB - 1002 - 01

18112
 001

Complies with 21 CFR 1040.10 and 1040.11 except for deviations pursuant to Laser Notice No. 50, Dated June 24, 2007.
 Apparätet må tilkoplas jordet stikkontakt
 Apparaten skall anslutas till jordat uttag
 Laite on liitettävä suojamaadoituskorkettimilla varustettuun pistorasiaan

HP, HQ - TRE, 71004
 Boeblingen, Germany

KGHM METRACO S.A.

 801/0/0063/4
 Drukarka CE956A
 Lokalizacja: HYDROM.


 This product includes HP
 Radio: SDGOB-0892

SCT: RCPHPSD09-0368
 CMIIT ID: 2009DJ0895
 IC: 466D-SDGOB892
 CNC: C - 7248

Complies with IDA
 Standards DB100427

FCC ID: B94SDGOB0892
 This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:
 (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

ANATEL
 0220-09-1130
 0107893552001792

ICA
 TA - 2008/1488
 APPROVED

RU6-8182