

FOTO 1



FOTO 2



FOTO 3





FOTO 4



FOTO 5

E





F

FOTO 6





FOTO 8






FOTO 9





A black and white photograph showing a close-up, low-angle view of a damaged roof structure. Several dark wooden beams are visible, some running diagonally across the frame. The roof is covered with corrugated metal sheets, many of which are missing or damaged, revealing the underlying structure. The lighting is dramatic, with strong highlights and deep shadows. The overall impression is one of significant structural damage and decay.

K

FOTO 11