

**Appendix no. 6 to the Interim Report on Implementation of the Land Acquisition and Resettlement Action Plan (LARAP) for Contract 3A.2 Flood protection in Serafa Valley encompassing the implementation of 2 Works Contracts:**

- 3A.2/1 – Flood protection in Serafa Valley – Malinówka 1 reservoir**
- 3A.2/2 – Flood protection in Serafa Valley – Malinówka 2 reservoir**



Foto. 1. *Malinówka 1 reservoir*, September 2021  
(view of the area of the planned reservoir before Works commencement).



Foto. 2. *Malinówka 1 reservoir*, September 2021  
(view of the area of the planned reservoir before Works commencement).





Foto. 3. *Malinówka 1 reservoir*, second decade of December 2021  
(reconstruction of the sewage system - securing excavations).



Foto. 4. *Malinówka 1 reservoir*, second decade of January 2022  
(forming a topsoil pile, marking the pile).





Foto. 5. *Malinówka 1 reservoir*, second decade of March 2022  
(place of storage of materials, access to sanitary facilities).



Foto. 6. *Malinówka 1 reservoir*, first decade of April 2022  
(fenced archaeological site, in the background fencing of trees not intended for felling).





Foto. 7. *Malinówka 1 reservoir*, second decade of May 2022  
(fenced archaeological site after documentation - completion of archaeological works).




Foto. 8. *Malinówka 1 reservoir*, second decade of June 2022  
(reinforcement for foundation of the discharge and overflow device).





Foto. 9. *Malinówka I reservoir*, third decade of August 2022  
(forming the embankment - embanking the reservoir).



Foto. 10. *Malinówka I reservoir*, second decade of March 2023  
(condition of public roads - keeping them clean).





Foto. 11. *Malinówka 1 reservoir*, second decade of September 2023  
(view of the reservoir bowl - grass growth, oak island).



Foto. 12. *Malinówka 1 reservoir*, third decade of September 2023  
(completed work).





Foto. 13. *Malinówka 2 reservoir*, second decade of December 2021  
(tree cutting, information board).



Foto. 14. *Malinówka 2 reservoir*, third decade of December 2021  
(fencing the area excluded from cutting).





Foto. 15. *Malinówka 2 reservoir*, third decade of January 2022  
(marking the zone under the power line, in the background - the trees fence).



Foto. 16. *Malinówka 2 reservoir*, third decade of March 2022  
(herpetological fences around the pond, next to the fence of the area excluded from cutting).





Foto. 17. *Malinówka 2 reservoir*, third decade of April 2022  
(herpetological fences around the pond)



Foto. 18. *Malinówka 2 reservoir*, third decade of May 2022  
(maintaining fences for trees excluded from felling)





Foto. 19. *Malinówka 2 reservoir, first decade of November 2022*  
(work in the reservoir bowl)



Foto. 20. *Malinówka 2 reservoir, third decade of December 2022*  
(discharge and overflow device, reservoir bowl)





Foto. 21. *Malinówka 2 reservoir*, third decade of September 2023  
(discharge and overflow device, reservoir bowl – works completion)