

## Appendix 2 to the Final Report

### Photographic Documentation of Selected PZŚ Measures Implemented During the Contract Execution



Photo 1. Prevention of HIV-AIDS Diseases and Raising Awareness about Mobbing



Photo 2. Electrofishing Conducted in Areas Isolated by a Sheet Pile Wall, Supervised by a Nature Monitoring Specialist



Photo 3. Construction Site Facilities Equipped with Containers of Sorbent and Sorbent Mats



Photo 4. Occupational Health and Safety (OHS) Information Board Installed at the Construction Site Facilities During the Project Implementation





Photo 5. Example of the Use of Herpetological Fences at the Project Site, Also Serving as Barriers for the Protection of Natural Habitats



Photo 6. Hardening of Machine Parking Areas Using Foil and Plates





Photo 7. Marking of Vehicle Refueling Stations



Photo 8. Archaeological Works at the Site of the Discovery of a Medieval Chainmail Armor





Photo 9. Amphibian Capture Operations Conducted by a Nature Monitoring Specialist



Photo 10. Activities Related to Identifying Invasive Species in the Project Area, Conducted by a Nature Monitoring Specialist





Photo 11. Grass Growth on the Seeded Slopes of Embankment No. I



Photo 12. Grass Growth on the Seeded Slopes of Embankment No. VI





Photo 13. Tree Plantings Carried Out on Municipal Land in Krosno Odrzańskie (Floodplain) as Part of Compensatory Measures for Trees Removed During Preparatory Works



Photo 14. Tree Plantings Carried Out on Municipal Land in Krosno Odrzańskie (Floodplain) as Part of Compensatory Measures for Trees Removed During Preparatory Works (Flood in September 2024)





Photo 15. View of Newly Constructed Flood Protection Embankments (Result of Flood Protection Measures Related to the September 2024 Flood)





Photo 15. View of Newly Constructed Flood Protection Embankments (Result of Flood Protection Measures Related to the September 2024 Flood)